

2011 Flood Projects

Highway	Description
Gravel Pit	Drainage repairs – Pilot Butte Pit
1	Culvert repairs - west of Wapella
1	Culvert repairs - 16 km east of Whitewood
1	Culvert repairs - 17 km east of Grenfell
1	Culvert repairs - 6 km east of Grenfell
1	Shoulder washout repairs – West of Wolseley
1	Culvert repairs – west of Wolseley
1	Culvert repairs – east of Indian Head
1	Landslide repairs – east of Regina
1	Culvert extension – west of Moosomin
1	Culvert repairs – White City north service road
1	Surface repairs - south service road west of White City
1	Overpass repairs – Belle Plaine
2	Surface repairs – 10 km north of Liberty
2	Surface repairs – Liberty to Young
2	Surface repairs – Watrous to Young
2	Surface repairs – 3 km north of Watrous
2	Surface repairs – 7 km north of Watrous
2	Surface repairs – south of Meacham
2	Culvert repairs – north of Meacham
2	Traffic control - north of Meacham
2	Culvert installation - north of Meacham
2	Grade raise - 3.5 km north of Jct. 5
2	Deep patch and hot-mix - north of Wakaw
2	Culvert replacement - north of Wakaw
2	Culvert repairs - north of Wakaw
2	Deep patching, AC overlay - 5.0 km N. of St. Louis to S. of Jct. Hwy 11

- 2 Culvert replacements - between Paddockwood and Prince Albert
- 2 Base patching, seal coat - Paddockwood Access
- 2 Culvert replacements - Paddockwood Access
- 2 Traffic control - approx. 12 km north of Christopher Lake Access
- 2 Culvert replacement - 1.25 km N. of Montreal Lake Access
- 2 Minor repairs - Napatak Access
- 2 Traffic control and erosion repairs - near Montreal River Bridge
- 2 Traffic control - Big Stone Lake Access
- 2 Surface repairs - near Montreal Lake Campground
- 3 Base patching, seal coat - Star City Access
- 3 Base patching, seal coat - Valparaiso Access
- 3 Culvert replacement - Soltechuks Slough
- 3 Culvert replacement - Kilwinning Grid
- 4 Deep patching - north of Biggar
- 4 Traffic control - south of Kyle
- 5 Surface repairs – east of Wadena
- 5 Surface repairs - Wadena to Quill Lake
- 5 Surface repairs – Leroy Access
- 5 Culvert repairs - Leroy Access
- 5 Surface repairs – west of Humboldt
- 5 Culvert repairs and installations - east of Saskatoon
- 5 Surface repairs – Togo to Jct. Hwy 57
- 5 Bridge repairs - at Kamsack
- 5 Culvert repairs – 22 km west of Kamsack
- 5 Surface repairs – east and west of Buchanan
- 5 Culvert repairs – west of Buchanan
- 5 Culvert repairs – west of Rama
- 5 Surface repairs – Watson to Muenster
- 6 Landslide repair – south of Ceylon

- 6 Culvert repairs – north of Ceylon
- 6 Surface repairs – north of Ceylon
- 6 Culvert repairs – north of Pangman
- 6 Surface repairs – north of Raymore
- 6 Culvert repairs – north of Raymore
- 6 Surface repairs – south of Watson
- 6 Bridge repair – south of Watson
- 6 Landslide base patching, seal coat - North of Melfort - vicinity of Melfort Creek.
- 6 Base patching, seal coat - Fairy Glen Access
- 6 Washout repairs - White Fox River
- 6 Surface repairs - north and south of Southey
- 8 Culvert repairs – south of Moosomin
- 8 Culvert repairs – north of Moosomin
- 8 Culvert repairs – near Rocanville
- 8 Surface repairs/shoulder washout repairs – Qu’Appelle River
- 8 Surface repairs - Tantallon Access
- 8 Surface repairs – Jct. Hwy 22 to Langenburg
- 8 Culvert repairs – 18 km north of Langenburg
- 8 Culvert repairs – south of Jct. Hwy 10
- 8 Culvert repairs – north of Hwy 10
- 8 Culvert repairs at Kamsack
- 8 Culvert repairs – 10 km north of Kamsack
- 8 Culvert repairs – 12 and 14 km north of Kamsack
- 8 Culvert repairs – 10 km north of Norquay
- 8 Culvert repair – 32 km north of Norquay
- 9 Landslide repair – south of Whitewood
- 9 Shoulder erosion and bridge repairs – Souris River
- 9 Pipestone slide repairs - S. of Whitewood
- 9 Traffic control - at Jct. Hwy 247

- 9 Culvert repairs – 16 km north of Jct. Hwy 247
- 9 Culvert repairs – 12 km north of Jct. Hwy 22
- 9 Surface repairs – Jct. Hwy 15 to 19 km north
- 9 Culvert repairs – 12 km north of Jct. Hwy 15
- 9 Surface repairs –Yorkton to 14 km south
- 9 Culvert repairs – south of Gronlid Access
- 9 Traffic control – south of Canora
- 9 Drainage repairs –south of Canora
- 9 Traffic control – north of Canora
- 9 Surface repairs – Usherville to forest boundary
- 9 Surface repairs – Forrest Boundary to Hwy 983
- 10 Erosion repairs – southwest of Fort Qu’Appelle
- 10 Surface repairs - northeast of Balgonie
- 10 Culvert repairs – 18 km west of MB border
- 10 Culvert repairs – 19 km west of Jct. hwy 80
- 10 Culvert repairs – 8 km west of Jct. Hwy 9
- 10 Culvert repairs – 4 km south west of Melville
- 10 Culvert repairs – 20 km southwest of Melville
- 11 Surface repairs - west of Disley access
- 12 Deep blading and patching - south of Martensville
- 12 Culvert repairs - north of Newhorst
- 12 Base patching, seal coat - Leask Grid #792 to Shell Lake
- 13 Surface repairs - Forget Access
- 13 Surface repairs – East of Weyburn
- 13 Culvert repairs - West of Weyburn
- 14 Bridge abutment repairs - near Kinley
- 15 Road repairs – Melville to Fenwood
- 15 Surface repairs – Southeast of Ituna
- 15 Culvert repairs – Southeast of Ituna

- 15 Surface repairs – West of Ituna
- 15 Surface repairs – East of Raymore
- 15 Shoulder repairs – West of Nakomis
- 15 Shoulder repairs – East of Kenaston
- 15 Backhoe work west of Kenaston
- 15 Deep patching and regravelling - near Conquest Access
- 15 Surface repairs – west of Semans to south Jct. Hwy 20
- 15 Surface repairs – Bredenbury to Jct. Hwy 9
- 16 Culvert repairs – Langenburg
- 16 Surface repairs – Yorkton
- 16 Shoulder repairs – Near Sheho
- 16 Shoulder and culvert repairs – West of Foam Lake
- 16 Culvert repairs – Near Leslie
- 16 Surface repairs – Near Wynyard
- 16 Shoulder repairs – Near Lanagan
- 16 Surface repairs – Jansen Access
- 16 Install approach culverts - from Saskatoon City limits to Struan Road
- 16 Culvert replacement - near Borden
- 18 Surface repairs – Frobisher to Bienfait
- 18 Surface, shoulder and bridge Repairs – West of Estevan
- 18 Surface repairs – Boundary Power Plant Access Road
- 18 Culvert repairs – West of Oungre
- 18 Culvert repairs – West of Highway 6
- 18 Landslide repairs – East of Big Beaver
- 18 Culvert repair - near Divide
- 19 Surface repairs – north of Mistusinne to Elbow
- 19 Surface repairs – north of Elbow to Loreburn
- 20 Surface repairs – north of Nokomis
- 20 Surface repairs – south of Humboldt

20 Traffic control – south of Humboldt

20 Surface repairs – Duval to south Jct. Hwy 15

20 Culvert repairs – south of south Jct. Hwy 15

20 Culvert repairs – South of Humboldt

20 Traffic control – north of Humboldt

21 Traffic control - south of Unity

21 Culvert replacement - south of Unity

21 Culvert repairs – 14 km north of U.S. border

22 Surface repairs – Manitoba Border to Hwy 8

22 Culvert repairs – west of Manitoba Border

22 Surface repairs – Hwy 8 to Stockholm

22 Surface repairs –west of Hwy 8

22 Surface repairs – west of Esterhazy

22 Surface repairs – Mosaic to Hwy 8

22 Surface and culvert repairs – Hwy 9 to 47

22 Culvert repairs – 3 km west of Hwy 9

22 Surface repairs – Hwy 47 to Hwy 10

22 Culvert cleaning – west of Hwy 47

22 Culvert repairs – west of Hwy 47

22 Surface repairs – 18 km west of Hwy 47

22 Surface repairs due to Hwy 1 detour – Hwy 47 to Hwy 10

22 Emergency response – Hwy 47 to Hwy 10

22 Surface repairs – Dysart to Southey

22 Culvert repairs – west of Cupar

22 Surface repairs - Southey to 5 km west

22 Surface repairs – 5 km west of Southey to Jct. Hwy 20.

23 Surface repairs – west of Carraganna access

24 Base patching, seal coat - Jct. Hwy 3 to Leoville

25 Deep patching, base patching – Southwest of Birch Hills

27 Deep patching - east of Aberdeen

- 31 Traffic control - west of Herschel
- 33 Surface repairs – northwest of Fillmore
- 33 Culvert repairs - Osage Access
- 33 Surface repairs – Kronau Service Road
- 34 Landslide repairs – south of Bengough
- 35 Surface repairs – south of Francis
- 35 Surface repairs – north of Francis
- 35 Base patching, seal coat - Sylvania Access
- 35 Culvert repairs - Ridgedale Access
- 35 Base patching, seal coat - Alysham Access
- 35 Base patching, seal coat - Tobin Lake Access (West side)
- 35 Surface repairs – Hwy 48 to Qu'Appelle
- 35 Culvert repairs – 19 km north of Hwy 48
- 35 Culvert repairs – 10 km north of Hwy 1
- 35 Surface repairs at Jct. Hwy 10
- 35 Surface repairs – 8 km to 16 km north of Hwy 10
- 35 Surface repairs – north of Lipton to south of Leross
- 35 Culvert repairs – north of Lipton
- 35 Culvert repairs – near Wishart Access
- 35 Surface repairs – 10 km north of Wishart Access
- 35 Drainage repairs – south of Elfros
- 35 Surface repairs – south of Elfros
- 35 Culvert failures – Wishart Access
- 35 Traffic control – 17 km north of Elfros
- 35 Culvert repair – 18 km north of Elfros
- 35 Culvert repair – 18 km north of Wadena
- 35 Surface repairs – Jct. Hwy 49 to Rose Valley
- 35 Surface repairs – Wishart Access
- 36 Bridge repair – north of Willowbunch

- 36 Slide repairs – south of Willowbunch
- 38 Surface repairs – Kelvington – 23 km north
- 38 Culvert repairs – 13 km north of Kelvington
- 38 Surface repairs – north of Kuroki to south of Waden
- 38 Culvert repairs -14 km north of Kuroki
- 38 Surface repairs – south of Kelvington
- 38 Surface repairs – south of Kelvington
- 39 Bridge repairs – Souris River
- 39 Surface repairs - Roche Percee Access
- 39 Surface repairs - Bienfait Connector
- 39 Grade raise – near Macoun
- 39 Sideslope repairs – north of Halbrite
- 39 Culvert repairs – south of Weyburn
- 39 Culvert repairs – north of Weyburn
- 39 Culvert repairs – east and West of Wilcox
- 41 Hand and machine patching - Ethelton E. of Yellow Creek
- 42 Deep patching - near Lucky Lake
- 42 Surface repairs – Tuxford to Keeler
- 42 Surface repairs – Keeler to west of Eyebrow
- 44 Deep patch - east of Loreburn
- 44 Deep patch and base overlay - Jct. of 44 & 219
- 44 Deep patch and claycap - west of Macrorie
- 44 Traffic control - east of Eston
- 45 Deep patch and base overlay - south of Jct. 44
- 45 Deep patching - north of Birsay
- 45 Deep patching - south of Outlook
- 45 Deep patching - north of Jct. 15 & 45
- 45 Deep patching - 2 km north of Swanson
- 47 Bridge repair – south of Estevan

- 47 Culvert repairs – north of Benson
- 47 Surface repairs - north of Stoughton
- 47 Culvert repairs – south of Grenfell
- 47 Surface repairs – south of Melville Beach
- 47 Surface repairs due to Hwy 1 detour –Melville Beach to Melville
- 47 Surface repairs – Melville to 18 km north of Willowbrook
- 47 Culvert repairs – 8 km north of Melville
- 47 Culvert repairs – 16 km north of Melville
- 47 Culvert cleaning – 28 km north of Melville
- 47 Surface repairs – Willowbrook to Springside
- 47 Surface repairs – 5 km north of Hwy 52
- 47 Surface repairs – Springside to Hwy 229
- 47 Culvert repairs – 1 km north of Hwy 16
- 47 Surface repairs – 6 km north of Hwy 16
- 47 Culvert and surface repairs – South of Buchanan
- 47 Surface repairs – Good Spirit Lake to Buchanan
- 47 Surface repairs – 10 km north of Hwy 16
- 47 Surface repairs – 12 km north of Hwy 16
- 47 Surface repairs – south of Buchanan
- 47 Grade raise, strengthen – Buchanan to Preeceville
- 47 Culvert repairs – 2 km north of Buchanan
- 48 Culvert repairs – West of Fairlight
- 48 Culvert repairs – Near Kennedy
- 48 Surface repairs – Kipling to East of Glenavon
- 48 Surface repairs – Montmarte to West of Odessa
- 48 Surface repairs - Vibank Service Road
- 49 Culvert repairs – 2 km west of Norquay
- 49 Culvert repairs – 7 km west of Preeceville
- 49 Surface repairs – 28 km west of Preeceville

52	Road repairs – Yorkton to Willowbrook
52	Road repairs – Willowbrook to Homefield
52	Surface repairs – Yorkton to Ituna
52	Surface repairs – Yorkton to Hwy 47
52	Culvert repairs – west of Jct. Hwy 15
52	Surface repairs – Jct. Hwy 15 to 17 km east
55	Grade raise - Rice River and Unnamed Creek
55	Grade raise - Red Earth Access
55	Culvert replacement - 8.5 km W of Choiceland
55	Culvert replacement - near Shellbrook
55	Culvert replacement north of Canwood
55	Culvert repairs – north of Canwood
55	Culvert repairs - Old Canwood Highway
56	Culvert repairs – 4 km and 8 km north of Indian Head
56	Culvert repairs – 5 km north of Indian Head
56	Culvert repairs – 20 km north of Hwy 1
56	Sideslope repairs – 11 km north of Hwy 1
57	Surface repairs – Manitoba Border to Hwy 5
57	Culvert repairs – 5 km west of Manitoba Border
58	Grade raise - 5 km south of Jct 363
60	Culvert replacement – south of Saskatoon
60	Traffic control – south of Saskatoon
80	Surface repairs – Esterhazy to Mosaic K1
80	Surface repairs – Mosaic K1 to Churchbridge
80	Surface repairs – Churchbridge to Wroxton
102	Traffic control -various locations north of La Ronge on Stanley Mission Rd
102	Surface repairs - approx. 5 km south of Stanley Mission Access
106	Surface repairs - Snowden Access
106	Minor Repairs - Various locations: including approx. 35 km northeast of Jct. Hwy 165 and approx. 20 km southwest of Jct. Hwy 911 (Deschambault Lake Access) ("new" km 32, km 72)

120 Bridge abutment repairs - White Gull Creek

120 Abutment repair Hwy 120 Torch River Bridge

123 Base patching, seal coat - N. of Jct. Hwy 55 to EB Campbell Dam

123 Base patching, grade raise - E.B.Campbell Dam to S end of SK river Bridge

123 Base patching, grade raise - East of E.B. Campbell Dam

123 Culvert replacement - Sipanook Channel

123 Base patching, seal coat - N. of Saskatchewan River Br. to Cumberland House

135 Minor repairs - various locations from Jct. Hwy 106 to Sandy Bay

135 Culvert repairs - Nemei River (11 km south of Sandy Bay)

165 Culvert repair - approx. 15 km east of Jct. Hwy 914

165 Traffic control - various locations from Jct. Hwy 2 to Jct. Hwy 910 (Besnard Lake Road)

165 Traffic control -various locations from Jct. Hwy 910 (Besnard Lake Road) to Jct. Hwy 914 (Pinehouse Road)

201 Surface repairs – Broadview to Hwy 247

201 Surface Repairs – 10 km north of Broadview

202 Culvert repairs – 7 km north of Jct. hwy 2

202 Surface repairs – 7 km north of Jct. Hwy 2

210 Surface repairs – Jct Hwy 10 to Jct. Hwy 56

211 Deep patching on Blackstrap Provincial Park access

220 Surface repairs – Rowan’s Ravine Access

224 Culvert repairs West of Greig Lake Access

225 Surface repairs – 18 km west of Hwy 2

229 Culvert install – 10 km west of Hwy 9

229 Surface repairs – at Hwy 9

229 Surface repairs – Good Spirit Lake to Hwy 47

229 Surface repairs – Good Spirit Lake to Hwy 47

240 Deep patching and seal coat - Jct. Hwy 55 to P.A.N.P. South Bndry

247 Surface repairs – Hwy 9 to Hwy 47

247 Surface repairs – Hwy 9 to Hwy 47

247 Landslide repairs – 10 km west of Hwy 9

247 Surface repairs – 40 km west of Hwy 9
247 Culvert install – east of Hwy 47
255 Base patching, seal coat - Tobin Lake Access (East side)
271 Surface repairs – Maple Creek to Forth Walsh Access
271 Slide repair – Fort Walsh Access
302 Base patching and seal coat - Weldon Ferry to Grid 780
302 Deep patching, AC overlay - Grid 780 to Prince Albert
304 Minor repairs near Jct. Hwy 4
305 Deep patching near Dalmeny
306 Bridge repairs – west of Colfax
306 Surface repairs – Lewvan to Riceton
308 Culvert repairs – West of Welwyn
309 Culvert install – 15 km east of Hwy 9
310 Culvert repairs – 9 km north of Balcarres
310 Culvert repairs – 14 km north of Balcarres
310 Surface repairs – 17 km north of Balcarres to south of Ituna
310 Surface repairs – Jct. Hwy 52 to 33 km north
310 Culvert repairs – north of Jct. Hwy 52
310 Shoulder repairs – north of Foam Lake
312 Deep patching - east of Rosthern
312 Culvert repairs - east of Rosthern
318 Surface repairs – North of Carnduff
321 Surface repairs – Jct. Hwy 21 to Burstall
322 Surface repairs – Jct. Hwy 20 to Jct. Hwy 220
334 Bridge Repairs – east of Avonlea
343 Surface repairs – Jct. Hwy 4 to 4 km west
349 Surface repairs – Jct. Hwy 38 to 11 km west
349 Culvert repairs – 9 km west of Archerwill
349 Culvert repairs – 28 km west of Archerwill

350 Bridge repairs and grade raise - Long Creek

355 Culvert repairs - east of Spruce Home to Albertville

357 Surface repairs – Togo to Hwy 8

357 Culvert repairs – 18 km west of Togo

361 Culvert repairs – east of Storthoaks

361 Surface repairs – Storthoaks to Highway 9

361 Culvert repairs – west of Storthoaks

364 Surface repairs – south of Edenwold to Edgeley

364 Surface repair – east of Edenwold

365 Surface repairs – Watrous to Hwy 16

365 Culvert repairs – north of Manitou Beach

369 Surface repairs – Hwy 10 to Togo

378 Base patching and seal coat - Jct Hwy 324 to Rabbit Lake

378 Base patching and seal coat- Rabbit Lake to 6.20 km E.

379 Surface repairs – McMahon to 14 km west

381 Grade raise – Manitoba Border to Hwy 80

381 Surface repairs – 1 km west of Manitoba Border

381 Surface repairs – 9 km west of Manitoba Border

910 Minor repairs - various locations from Jct. 165 to Besnard Lake

912 Washout repairs - Wapawekka Road

912 Culvert repairs – at Wapawekka Road

913 Erosion repair at culvert inlet - White Swan Road

914 Minor repairs - various locations from Jct. 165 to north of Pinehouse

915 Minor repairs - various locations on Stanley Mission Rd

916 Washout repairs at various locations on Elaine Lake Road

920 Repair bridge abutment – north of Lower Fishing Lake

921 Washout repairs Randall Lake Road

922 Replace culvert - Nesslin Lake Access

922 Washout repairs - Nesslin Lake Access

- 926 Culvert repair washout - at Hanin Creek
- 926 Washout repairs – south of Candle Lake
- 936 Culvert repairs - at Tracey Road washed and other locations.
- 937 Erosion and surface repairs - Pear Lake Road
- 939 Erosion and surface repairs - Rock Lake Road
- 953 Culvert repairs - Anglin Lk. Road (Approx. 12 km north of Hwy 263)
- 969 Culvert repairs - approx. 50 km north of Timber Cove
- 969 Repairs due to water over road at approx 25 locations.